

## Risk of mixing up the tension pulleys

Technical Info No. 1756

### Vehicle manufacturers:

Opel, Vauxhall, Holden

### Items affected:

No.	RUVILLE no.	OE no.	Manuf. no.
1	55306	56 36 738	97 91 95
2	55342	6 36 729	97 94 88

### Important note:

The pretensioning force and the damping of the tension pulleys are not identical!  
In the event of incorrect assignment, there is the risk that the toothed belt will jump, causing damage to the engine!

Make sure when installing the above-mentioned tension pulleys that the correct vehicle is assigned. Both types are identical in external appearance.



However, the tension pulley 55342 has a larger working/adjustment range and a high-temperature bearing. It is therefore suitable for "hot" regions (e.g. Asia, Australia).



The tension pulleys can be distinguished by the manufacturer's number (red arrow) stamped on the reverse side.